

NEW

Flexible Clamp Meter MODEL 3570

FEATURES

- AC Current measureable max upto 3000A
- Flexible clamp sensor for measurement in hard to clamp areas.
- TRMS for accurate measurements on Non sinusoidal waveforms
- Min/Max & Data Hold
- Backlight Display
- Instrument meets EN61010 CAT IV 600V/
CAT III 1000V



CE

SPECIFICATIONS

Measurement range (AC A TRMS)	30/300/3000A
Resolution	0.01A/0.1A/1A
Accuracy	±3%rdg±5dgt[45-500Hz]
Conductor Size	Approx Ø 150mm(max)
Influence of Conductor position	Additional ±3%(max) depending on the distance from the center position
Applicable standards	CAT IV 600V, CAT III 1000V, EN 61010-1; EN 61010-2-032 EN 61326-1; EN 61000-4
Operating temperature/ humidity	0°C - +50°C, less than 80% RH (without condensation)
Power source	LR03(AAA)(1.5V)×2 or UM-4
Dimensions & Weight	Display unit : 120(L)×70(W)×26(D) Cable length : 1.8m approx.
Accessories	Model No. AR-35 (Carrying Case) Battery (1.5V AAA x 2) Instruction Manual